


# QUICK START for the AC-1-4



- 1 Connect the (4) conductors from the POWER/CAN side of the module only  
Leave the other wires unconnected and make sure they are not touching each other.



- 2 Make sure you have 6VDC to 30VDC between SUPPLY + (red) and GND (black)

- 3 Connect CAN H (blue) and CAN L (white) to your system

**!** Do not apply more than 5V on any analog input!

- 4 Be sure you have 120 ohm termination resistors on each end of the bus and nodes no longer than 0.3 meter

\*per CAN Specification for 1Mbit/s rate

- 5 You should see the CAN messages streaming on your CAN viewer (set at 1Mbit/s bit rate)